Bode Analyzer Suite 3.50

Bugfixes from version 3.25 SR2 to 3.50

Bug ID	Description
184547	Recalculate measurement trace values retroactively can lead to deviation at frequencies below 100 Hz
286941	Copying a memory breaks admittance and reflection calculation
148616	Bode Analyzer Suite sometimes crashes at startup

Known Issues

Known issues in **Bode Analyzer Suite 3.50** that will be resolved in future:

Bug ID	Description	Current workaround