

Bode Analyzer Suite 3.51

Bugfixes from version 3.50 to 3.51

Bug ID	Description	
243007	Changing transfer function representation in circuit fit might result in errors.	
338179	Expression Editor: Trace names containing "=" lead to parsing errors.	
	Solution: "=" cannot be used.	
329356	If a Bode 500 connected via USB is not accessible via network user is now	
	informed via Warning message.	
333730	Bode Analyzer crashed in some cases when using cursors in Nyquist chart.	
324814	Improved stability of Bode Analyzer Suite in case of corrupted WMI on	
	Windows.	
330107	Improved stability of Bode Analyzer Suite in case of .bode3 file loading.	

Known Issues

Known issues in **Bode Analyzer Suite 3.51** that will be resolved in future:

Bug ID	Description	Current workaround

Information_BAS-3_51.docx 2025-04-01 Page 1 of 1